



# Project Overview

## FRP REPAIR OF DETERIORATED WOOD BEAM

**Name:** Kinder Morgan Plant Glulam Beam  
**Type:** Wooden Beam  
**Location:** Tampa, Florida  
**Completed:** December 2009

### PROBLEM

Leakage and very damp environment had caused deterioration of this large glulam beam in a plant. The end of the beam was split, compromising the load-carrying capacity of the beam.



### SOLUTION

QuakeWrap® engineers developed a repair system and provided the materials to fix the beam as detailed below:

1. QuakeBond™ J201TC was placed between all the layers of timber and the beam was temporarily clamped with 5 external steel clamps to press all sections together as shown on the right.
2. QuakeWrap® VU18C carbon fabric was saturated with QuakeBond™ J300SR Saturating Resin and the bands were wrapped around the beam in regions between the clamps.
3. A day later after the epoxy had cured, the steel clamps were removed and the remaining portions of the beam were repaired similar to the procedure mentioned in Step 2 above.



The finished beam is shown in the photograph below.



## Technical Highlights

- FRP repair provided to glulam beam to correct severe deterioration of the wooden glulam beam.
- Repair work done with minimal disruption to the plant operations.
- The original strength of the beam was re-restored.



## Credits

Structural Engineer: QuakeWrap, Inc.  
Material Supplier: QuakeWrap, Inc.  
Contractor: Premier Corrosion

*“The FRP Retrofit Experts”*

— © 2009 QuakeWrap, Inc. | (520) 791-7000 —